



# Statistical Process Control


Kvalitetsflow 2015

# Suggested Program

Day 1		
<b>08.00-09.50</b>	8.00-8.30	Welcome – Presentation and introduction
	8.30-8.55	Over view of SPC – The basics
	9.00 – 9.50	The reason for SPC – flow chart Variation
<b>Coffee</b>		
<b>10.10.-12.10</b>	10.10-11.00	SPC – Cpk – Six Sigma – short discussion
	11.05-12.10	What type of chart in different situations
<b>Lunch</b>		
<b>12.40-15.00</b>	12.45-13.15	Setting up SPC Systems
	13.20-14.15	Checklist : Ready to measure ?
	14.20-14.40	Discussion – What do need the most ?
	14.50-15.00	Planning for day 2

# Suggested Program

Day 2		
<b>08.00-09.50</b>	8.00-8.30	Setting up SPC in QDA
	8.30-8.55	Make QDA fit to your data
	9.00 – 9.50	Case: try it on your data
<b>Coffee</b>		
<b>10.10.-12.10</b>	10.10-11.00	Case: try it on your data
	11.05-12.10	Analysis and reporting
<b>Lunch</b>		
<b>12.40-15.00</b>	12.45-13.15	Analysis and reporting
	13.20-14.15	Additional theory?
	14.20-14.40	Analysis on your data – setting up reports
	14.50-15.00	Evaluation and actions agreed



# Training in SPC and Setting up SPC in QDA

# Setting up a SPC in general

- Proces variables – how to find the relation between the proces variables and our SPC measure system.
- First things first – MSA (Measure system analysis) to approve the system before we collect all data make decision on "shaky ground"
- Collecting basic information about the proces
  - USL, LSL
  - UCL, LCL
  - CP and Cpk values and targets

# Setting up SPC i QDA

QDA 8.5

File Edit View ?

Number: 4

## Statistic Methods

Table Details

Statistical Method: Standard

Capability (Task/Machine) Capability (Gage) Control Chart Test of Distribution Tools

**Process Capability**

Sigma [Exp.] - Cp

Sbar/c4  
 Rbar/d2  
 S(tot)  
 Sbar2

Sigma [Exp.] - Pp

Sbar/c4  
 Rbar/d2  
 S(tot)  
 Sbar2

Sigma [Exp.] - Cpk

Sbar/c4  
 Rbar/d2  
 S(tot)  
 Sbar2

Sigma [Exp.] - Ppk

Sbar/c4  
 Rbar/d2  
 S(tot)  
 Sbar2

Cp-min: 1,66 Pp-min: 2  
 Cpk-min: 1 Ppk-min: 1,66  
 +/- sigma: 3 +/- sigma: 3

**Machine Capability**

Sigma [Exp.]

S(tot)  
 Sbar2  
 Rbar2  
 Sq/c4  
 Rq/d2

Cm-min: 1  
 Cmk-min: 1,33  
 +/- sigma: 4

**Additional decimals**

Xb: 1  
 Xbb: 2  
 Sigma: 3  
 Capability: 3


**Log-Cpk**

Ford  
 DGQ

User: Admin Station: KVALITETSFLOW () Database: Standard


# Six Sigma as a Metric

**Sigma =  $\sigma$  = Deviation**  
( Square root of variance )



between $\pm 1\sigma$	68.27 %	result: 317300 ppm outside (deviation)
between $\pm 2\sigma$	95.45 %	45500 ppm
between $\pm 3\sigma$	99.73 %	2700 ppm
between $\pm 4\sigma$	99.9937 %	63 ppm
between $\pm 5\sigma$	99.999943 %	0.57 ppm
between $\pm 6\sigma$	99.9999998 %	0.002 ppm

# Effect of 1.5 Sigma Process Shift






# Drift and combinations of PPM and sigma

- part per million.
- Green, indicates data that are normally used

Sigma Drift	3 $\sigma$	3.5 $\sigma$	4 $\sigma$	4.5 $\sigma$	5 $\sigma$	5.5 $\sigma$	6 $\sigma$
0 $\sigma$	2,700	465	63	3.4	0.57	0.034	0.002
0.25 $\sigma$	3,577	666	99	12.8	1.02	0.1056	0.0063
0.5 $\sigma$	6440	1382	236	32	3.4	0.71	0.019
0.75 $\sigma$	12228	3011	665	88.5	11	1.02	0.1
1 $\sigma$	22832	6443	1350	233	32	3.4	0.39
1.25 $\sigma$	40111	12201	3000	577	88.5	10.7	1
1.5 $\sigma$	66803	22800	6200	1350	233	32	3.4
1.75 $\sigma$	105601	40100	12200	3000	577	88.4	11
2 $\sigma$	158,700	66800	22800	6200	1300	233	32

# Problem Definition

- What do you want to improve?
- What is your 'Y'?



What are the *Goals*?

*Problem Definitions need to be based on quantitative facts supported by analytical data.*

Map the Process

Identify the variables - 'x'

Measure the Process

Understand the Problem -  
'Y' = function of variables - 'x'  
 $Y=f(x)$

*To understand where you want to be, you need to know how to get there.*

# Control Phase

How to create a Control Plan: (one suggestion...)

- Select Causal Variable(s). Proven vital few  $X(s)$
- Define Control Plan
  - 5Ws for optimal ranges of  $X(s)$
- Validate Control Plan
  - Observe  $Y$
- Implement/Document Control Plan
- Audit Control Plan
- Monitor Performance Metrics


# Control Phase

## Control Plan Tools:


- Statistical Process Control (SPC)
  - Used with various types of distributions
  - Control Charts
    - Attribute based (np, p, c, u). Variable based (X-R, X)
    - Additional Variable based tools
      - -PRE-Control
      - -Common Cause Chart (Exponentially Balanced Moving Average (EWMA))

# Control Phase


How do we select the correct Control Chart:




X Chart for strength



p Chart for ojdefects/ojsize



X-bar Chart for cereal



# Statistical Process Control (SPC)

- Invented by Walter Shewhart at Western Electric
- Distinguishes between
  - common cause variability (random)
  - special cause variability (assignable)
- Based on repeated samples from a process




# Statistical Process Control (SPC)

- A methodology for monitoring a process to identify special causes of variation and signal the need to take corrective action when appropriate
- SPC relies on control charts


# Variability

- Deviation = distance between observations and the mean (or average)
- Results for “Emmett”

	Observations	Deviations
	10	$10 - 8.4 = 1.6$
	9	$9 - 8.4 = 0.6$
	8	$8 - 8.4 = -0.4$
	8	$8 - 8.4 = -0.4$
	7	$7 - 8.4 = -1.4$
<b>averages</b>	<b>8.4</b>	<b>0.0</b>



Emmett




Jake

# Variability


- Deviation = distance between observations and the mean (or average)

- Results for "Jake"

	Observations	Deviations
	7	$7 - 6.6 = 0.4$
	7	$7 - 6.6 = 0.4$
	7	$7 - 6.6 = 0.4$
	6	$6 - 6.6 = -0.6$
	6	$6 - 6.6 = -0.6$
<b>averages</b>	<b>6.6</b>	<b>0.0</b>




Emmett




Jake

# Variability

- Variance = average distance between observations and the mean squared



Emmett



Jake


	Observations	Deviations	Squared Deviations
	10	$10 - 8.4 = 1.6$	2.56
	9	$9 - 8.4 = 0.6$	0.36
	8	$8 - 8.4 = -0.4$	0.16
	8	$8 - 8.4 = -0.4$	0.16
	7	$7 - 8.4 = -1.4$	1.96
averages	8.4	0.0	1.0

Variance


# Variability

- Variance = average distance between observations and the mean squared

	Observations	Deviations	Squared Deviations
	7		
	7		
	7		
	6		
	6		
averages			




Emmett



Jake


# Variability

- Variance = average distance between observations and the mean squared



Emmett

	Observations	Deviations	Squared Deviations
	7	$7 - 6.6 = 0.4$	0.16
	7	$7 - 6.6 = 0.4$	0.16
	7	$7 - 6.6 = 0.4$	0.16
	6	$6 - 6.6 = -0.6$	0.36
	6	$6 - 6.6 = -0.6$	0.36
averages	6.6	0.0	0.24




Jake


**Variance**

# Variability

- Standard deviation = square root of variance



Emmett




Jake

	Variance	Standard Deviation
Emmett	1.0	1.0
Jake	0.24	0.4898979

# Variability

The world tends to be bell-shaped



Even very rare  
outcomes are  
possible  
(probability > 0)



Fewer  
in the  
“tails”  
(lower)

Most outcomes  
occur in the  
middle

Fewer  
in the  
“tails”  
(upper)




Even very rare  
outcomes are  
possible  
(probability > 0)



# Variability

Here is why:

Even outcomes that are equally likely (like dice),  
when you add them up, become bell shaped




# “Normal” bell shaped curve

Add up about 30 of most things and you start to be “normal”

Normal distributions are divide up into 3 standard deviations on each side of the mean


Once your that, you know a lot about what is going on



# Causes of Variability

- Common Causes:
  - Random variation (usual)
  - No pattern
  - Inherent in process
  - adjusting the process increases its variation
- Special Causes
  - Non-random variation (unusual)
  - May exhibit a pattern
  - Assignable, explainable, controllable
  - adjusting the process decreases its variation


# 3 Sigma and 6 Sigma Quality



# Statistical Process Control


- The Control Process
  - Define
  - Measure
  - Compare
  - Evaluate
  - Correct
  - Monitor results
- Variations and Control
  - Random variation: Natural variations in the output of a process, created by countless minor factors
  - Assignable variation: A variation whose source can be identified

# Sampling Distribution




# Normal Distribution

$\sigma$  = Standard deviation



# Control Limits







# SPC Errors

- Type I error
  - Concluding a process is not in control when it actually is.
- Type II error
  - Concluding a process is in control when it is not.

# Type I Error




# Observations from Sample Distribution



# Control Chart


- Control Chart
  - Purpose: to monitor process output to see if it is random
  - A time ordered plot representative sample statistics obtained from an on going process (e.g. sample means)
  - Upper and lower control limits define the range of acceptable variation

# Control Chart





# Control Charts in General

- Are named according to the statistics being plotted, i.e.,  $\bar{X}$ , R, p, and c
- Have a center line that is the overall average
- Have limits above and below the center line at  $\pm 3$  standard deviations (usually)



Histograms do not take into account changes over time.



Control charts can tell us when a process changes

# Control Chart Applications

- Establish state of statistical control
- Monitor a process and signal when it goes out of control
- Determine process capability




# Commonly Used Control Charts

- Variables data
  - $\bar{x}$ -bar and R-charts
  - $\bar{x}$ -bar and s-charts
  - Charts for individuals (x-charts)
- Attribute data
  - For “defectives” (p-chart, np-chart)
  - For “defects” (c-chart, u-chart)

# Developing Control Charts

- Prepare
  - Choose measurement
  - Determine how to collect data, sample size, and frequency of sampling
  - Set up an initial control chart
- Collect Data
  - Record data
  - Calculate appropriate statistics
  - Plot statistics on chart



Use QDA it is much easier


# Next Steps

- Determine trial control limits
  - Center line (process average)
  - Compute UCL, LCL
- Analyze and interpret results
  - Determine if in control
  - Eliminate out-of-control points
  - Recompute control limits as necessary

# Limits

- Process and Control limits:
  - Statistical
  - Process limits are used for individual items
  - Control limits are used with averages
  - Limits =  $\mu \pm 3\sigma$
  - Define usual (common causes) & unusual (special causes)
- Specification limits:
  - Engineered
  - Limits = target  $\pm$  tolerance
  - Define acceptable & unacceptable

# Process vs. control limits



- Variance of averages  $<$  variance of individual items

# Variables Data Charts

- Process Centering

- X bar chart

- X bar is a sample mean

$$\bar{X} = \frac{\sum_{i=1}^n X_i}{n}$$

- Process Dispersion (consistency)

- R chart

- R is a sample range

$$R = \max(X_i) - \min(X_i)$$

# X bar charts

- Center line is the grand mean ( $\bar{\bar{X}}$  double bar)
- Points are  $\bar{X}$  bars

$$\sigma_{\bar{x}} = \sigma / \sqrt{n} \qquad \bar{\bar{X}} = \frac{\sum_{j=1}^m \bar{X}_j}{m}$$

$$UCL = \bar{\bar{X}} + z\sigma_{\bar{x}}$$

$$LCL = \bar{\bar{X}} - z\sigma_{\bar{x}}$$

-OR-

$$UCL = \bar{\bar{X}} + A_2 \bar{R}$$

$$LCL = \bar{\bar{X}} - A_2 \bar{R}$$



# R Charts

- Center line is the grand mean ( $\bar{R}$ )
- Points are R
- D3 and D4 values are tabled according to n (sample size)

$$UCL = D_4 \bar{R}$$

$$LCL = D_3 \bar{R}$$

# Use of $\bar{X}$ bar & R charts

- Charts are always used in tandem
- Data are collected (20-25 samples)
- Sample statistics are computed
- All data are plotted on the 2 charts
- Charts are examined for randomness
- If random, then limits are used “forever”

# Attribute Charts

- c charts – used to count defects in a constant sample size

$$\bar{c} = \frac{\sum_{i=1}^n c}{m} = \text{centerline}$$

$$LCL = \bar{c} - z\sqrt{\bar{c}}$$

$$UCL = \bar{c} + z\sqrt{\bar{c}}$$

# Attribute Charts

- p charts – used to track a proportion (fraction) defective

$$\bar{p} = \frac{\sum_{j=1}^m p}{m} = \frac{\sum_{ij} x}{nm} = \text{centerline} \frac{\sum_{i=1}^n x_i}{n}$$

$$UCL = \bar{p} + z \sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$


$$LCL = \bar{p} - z \sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

# Control Charts for Variables



- Mean control charts
  - Used to monitor the central tendency of a process.
  - X bar charts
- Range control charts
  - Used to monitor the process dispersion
  - R charts

Variables generate data that are measured.


# Mean and Range Charts



# Mean and Range Charts



Does not  
reveal increase



Reveals increase

# Control Chart for Attributes

- p-Chart - Control chart used to monitor the proportion of defectives in a process
- c-Chart - Control chart used to monitor the number of defects per unit

Attributes generate data that are counted.



# Use of p-Charts

- When observations can be placed into two categories.
  - Good or bad
  - Pass or fail
  - Operate or don't operate
- When the data consists of multiple samples of several observations each

# Use of c-Charts

- Use only when the number of occurrences per unit of measure can be counted; non-occurrences cannot be counted.
  - Scratches, chips, dents, or errors per item
  - Cracks or faults per unit of distance
  - Breaks or Tears per unit of area
  - Bacteria or pollutants per unit of volume
  - Calls, complaints, failures per unit of time

# Use of Control Charts

- At what point in the process to use control charts
- What size samples to take
- What type of control chart to use
  - Variables
  - Attributes

# Run Tests

- Run test – a test for randomness
- Any sort of pattern in the data would suggest a non-random process
- All points are within the control limits - the process may not be random


# Nonrandom Patterns in Control charts

- Trend
- Cycles
- Bias
- Mean shift
- Too much dispersion


# Typical Out-of-Control Patterns

- Point outside control limits
- Sudden shift in process average
- Cycles
- Trends
- Hugging the center line
- Hugging the control limits
- Instability

# Shift in Process Average




# Identifying Potential Shifts






# Cycles



# Trend




# Final Steps

- Use as a problem-solving tool
  - Continue to collect and plot data
  - Take corrective action when necessary
- Compute process capability


# Process Capability

- Tolerances or specifications
  - Range of acceptable values established by engineering design or customer requirements
- Process variability
  - Natural variability in a process
- Process capability
  - Process variability relative to specification


# Process Capability



**A. Process variability matches specifications**



**B. Process variability well within specifications**



**C. Process variability exceeds specifications**

# Process Capability Ratio


Process capability ratio,  $C_p = \frac{\text{specification width}}{\text{process width}}$

$$C_p = \frac{\text{Upper specification} - \text{lower specification}}{6\sigma}$$

# Improving Process Capability

- Simplify
- Standardize
- Mistake-proof
- Upgrade equipment
- Automate

# Taguchi Loss Function





# Meet the Guru: Taguchi

Taguchi  
Quality  
through  
design

- 1) Product must be robust to variation in process
- 2) Loss is equal to distance from nominal

## The "old" philosophy

Lower tolerance

Upper tolerance



## The "Taguchi" philosophy

Lower tolerance

Upper tolerance



# But in reality it looks like this ?

## The OK / NOK quality

Lower tolerance

Upper tolerance




# Limitations of Capability Indexes


- Process may not be stable
- Process output may not be normally distributed
- Process not centered but  $C_p$  is used

# Process Capability

- The ratio of process variability to design specifications




# Empirical Rule




# Gauges and Measuring Instruments

- Variable gauges
- Fixed gauges
- Coordinate measuring machine
- Vision systems


# Examples of Gauges




Vernier caliper



Digital caliper



Micrometer



One-inch digital electronic micrometer

# Metrology - Science of Measurement

- **Accuracy** - closeness of agreement between an observed value and a standard
- **Precision** - closeness of agreement between randomly selected individual measurements



# Repeatability and Reproducibility

- Repeatability (equipment variation) – variation in multiple measurements by an individual using the same instrument.
- Reproducibility (operator variation) - variation in the same measuring instrument used by different individuals

# Repeatability and Reproducibility Studies

- Quantify and evaluate the capability of a measurement system
  - Select  $m$  operators and  $n$  parts
  - Calibrate the measuring instrument
  - Randomly measure each part by each operator for  $r$  trials
  - Compute key statistics to quantify repeatability and reproducibility

# Reliability and Reproducibility Studies(2)

Measurement (M) made by  
Operators(i from 1 to m) on  
Parts (j from 1 to n) in

Trials (r from 1 to r)

**Use QDA it is**

$$\bar{x}_i = \frac{\left( \sum_j \sum_k M_{ijk} \right)}{n \cdot r} \text{ average for each operator}$$

$\bar{x}_D = \max_i (\bar{x}_i) - \min_i (\bar{x}_i)$  difference (range) of operator averages

$R_{ij} = \max_k (M_{ijk}) - \min_k (M_{ijk})$  range of each part for each operator

$$\bar{R}_i = \frac{\left( \sum_j R_{ij} \right)}{n} \text{ average range for each operator}$$

$$\bar{\bar{R}} = \frac{\left( \sum_i \bar{R}_i \right)}{m} \text{ average range of all}$$

**much easier**

## Reliability and Reproducibility Studies(3)

Control limit of ranges  $R_{ij} = D_4 \cdot \bar{\bar{R}}$

Use number trials (r) for n in table. Check for randomness of errors.

Repeatability or Equipment Variation

$EV = K_1 \cdot \bar{\bar{R}}$   $K_1$  is a constant tied to # of trials

Reproducibility or operator appraisal variation

$AV = \sqrt{(K_2 \cdot \bar{x}_D)^2 - \left(\frac{EV^2}{n}\right)}$   $K_2$  is a constant tied to # of operators

Repeatability and Reproducibility

$R \& R = \sqrt{(EV)^2 + (AV)^2}$

Results are in actual units measured. Customary to express as percentages.

Under 10% - Acceptable

10 - 30% - ? based on importance and repair cost

Over 30% - Unacceptable

**Use QDA it is much easier**


# R&R Constants

Number of Trials	2	3	4	5
$K_1$	4.56	3.05	2.50	2.21
Number of Operators	2	3	4	5
$K_2$	3.65	2.70	2.30	2.08


# R&R Evaluation

- Under 10% error - OK
- 10-30% error - may be OK
- over 30% error - unacceptable


# How do we know our process?



Process Map



Fishbone



Historical Data

## RATIONAL SUBGROUPS

Minimize variation within subgroups  
Maximize variation between subgroups


BLACK NOISE  
(Signal)

WHITE NOISE  
(Common Cause  
Variation)

PROCESS  
RESPONSE

TIME


**RATIONAL SUBGROUPING** Allows samples to be taken that include only white noise, within the samples. Black noise occurs between the samples.





# Visualizing the Causes


Within Group



$$\sigma_{st} + \sigma_{shift} = \sigma_{total}$$

- Called  $\sigma$  short term ( $\sigma_{st}$ )
- Our potential - the best we can be
- The s reported by all 6 sigma companies
- The trivial many

# Visualizing the Causes




$$\sigma_{st} + \sigma_{shift} = \sigma_{total}$$

Between Groups

- Called  $\sigma_{shift}$  (truly a measurement in sigmas of how far the mean has shifted)
- Indicates our process control
- The vital few

- Assignable Cause
- Outside influences
- Black noise
- Potentially controllable
- How the process is actually performing over time



Fishbone


- Common Cause Variation
- Variation present in every process
- Not controllable
- The best the process can be within the present technology

# Gauge R&R



$$\sigma^2_{\text{Total}} = \sigma^2_{\text{Part-Part}} + \sigma^2_{\text{R\&R}}$$

Recommendation:



Resolution £ 10% of tolerance to measure  
Gauge R&R £ 20% of tolerance to measure





- **Repeatability (Equipment variation)**
  - Variation observed with one measurement device when used several times by one operator while measuring the identical characteristic on the same part.
- **Reproducibility (Appraised variation)**
  - Variation Obtained from different operators using the same device when measuring the identical characteristic on the same part.
- **Stability or Drift**
  - Total variation in the measurement obtained with a measurement obtained on the same master or reference value when measuring the same characteristic, over an extending time period.





In many cases, the data sample can be transformed so that it is approximately normal. For example, square roots, logarithms, and reciprocals often take a positively skewed distribution and convert it to something close to a bell-shaped curve




# What do we Need?



*Off-Target, Low Variation  
High Potential Defects  
Good Cp but Bad Cpk*



*On Target  
High Variation  
High Potential Defects  
No so good Cp and Cpk*




*On-Target, Low Variation  
Low Potential Defects  
Good Cp and Cpk*

- Variation reduction and process centering create processes with less potential for defects.
- The concept of defect reduction applies to **ALL** processes (not just manufacturing)


## Eliminate “Trivial Many”

- Qualitative Evaluation
- Technical Expertise
- Graphical Methods
- Screening Design of Experiments



## Identify “Vital Few”

- Pareto Analysis
- Hypothesis Testing
- Regression
- Design of Experiments



## Quantify Opportunity


- % Reduction in Variation
- Cost/ Benefit

**Our Goal:  
Identify the Key Factors (x's)**






# Graph>Box plot

Without X values



# Graph>Box plot




Box plots help to see the data distribution

# Statistical Analysis


Apply statistics to validate actions & improvements

## Hypothesis Testing



Compare  
Sample Means  
& Variances

## Regression Analysis





Identify  
Relationships

Establish  
Limits

- Is the factor really important?
- Do we understand the impact for the factor?
- Has our improvement made an impact
- What is the true impact?

M.A.D



# Excercise

$$x_{\max} = \frac{v_0^2}{g} \cdot \sin(2 \cdot \alpha)$$

$$v_0 = \sqrt{\frac{x_{\max} \cdot g}{\sin(2 \cdot \alpha)}}$$

$$g = \frac{v_0^2}{x_{\max}} \cdot \sin(2 \cdot \alpha)$$

$$\alpha = \frac{1}{2} \cdot \sin^{-1} \left( \frac{x_{\max} \cdot g}{v_0^2} \right)$$

Symbol	Beskrivelse	Enhed
$x_{\max}$	Kastelængde	m (meter)
$v_0$	Begyndeshastigheden	$\frac{\text{m}}{\text{s}}$
$g$	Tyngdeaccelerationen	$g \approx 9,82 \frac{\text{m}}{\text{s}^2}$
$\alpha$	Affyringsvinklen	°